

FULL CAR INSPECTION REPORT

| | |
|---------------------|--------------------|
| Owner Name | Mr. AHMED AL SAIDI |
| Car Brand & Model | CADILLAC ESCALADA |
| Year of Manufacture | 2012 |
| Chassis Number | 1GYS47EFxxxxx293 |
| Plate Number | DUBAI U-87295 |

| KEY FINDINGS: | |
|----------------------------------|---|
| Critical Issues Found | None |
| Non-Critical Issues Found | <ol style="list-style-type: none">1. Front wheel bearing both side to be replaced2. Front shock absorber bushes to be replaced3. Steering tie rod end to be replaced4. Radiator coolant top-up5. Power steering tank oil cap to be replaced |

Job Estimate/ Quotation for Critical Items Submitted:

YES

NO ✓

Interior Disinfection Treatment Done:

YES

NO ✓

No. of Keys Available: 2

DATE: 26/OCT/2020

LOCATION: OPEN BONNET - AL QUOZ PARTNER

TECHNICIAN NAME: SACHIN

All information given in this report is valid and correct as of the date of the inspection.

| | |
|-------------------------------------|---|
| DETAILED INSPECTION FINDINGS | PASSED |
| | OK – Not Critical. Can be Repaired in Sometime |
| | FAILED – Critical. Need to Repair Urgently |
| | NA – Not Applicable |

| CAR BODY | | | |
|----------------------------------|---|--|--|
| Bonnet | ✓ | | |
| Front Bumper | ✓ | | |
| Left Fender | ✓ | | |
| Front Left Door | ✓ | | |
| Rear Left Door | ✓ | | |
| Left Rocker / Sill Panels | ✓ | | |
| Left Quarter Panel | ✓ | | |
| Trunk / Boot Door | ✓ | | |
| Rear Bumper | ✓ | | |
| Right Quarter Panel | ✓ | | |
| Rear Right Door | ✓ | | |
| Front Right Door | ✓ | | |
| Right Rocker / Sill Panels | ✓ | | |
| Right Fender | ✓ | | |
| Car Pillars | ✓ | | |
| Car Roof | ✓ | | |
| All Body Panels Properly Aligned | ✓ | | |
| Rear-view And Side view Mirrors | ✓ | | |
| Windshield | ✓ | | |
| Wiper Blades Front | ✓ | | |
| Wiper Blades Rear | ✓ | | |
| Convertible Top (If Applicable) | ✓ | | |
| Chassis | ✓ | | |
| All Mountings | ✓ | | |
| Body Bushing | ✓ | | |
| Frame rail and sub frame | ✓ | | |

* To get the best Estimate for Repair Work found on this car, please contact Open Bonnet at +971589512500

| ENGINE & TRANSMISSION | | | |
|------------------------------|---|---|--|
| Engine Oil | ✓ | | |
| Engine oil leak | ✓ | | |
| Engine compartment firewall | ✓ | | |
| Engine Fan(s) | ✓ | | |
| Brake Oil | ✓ | | |
| Clutch Oil | ✓ | | |
| Clutch Oil leak | ✓ | | |
| Gear Oil | ✓ | | |
| Gear Oil Leak | ✓ | | |
| Coolant | | ✓ | |
| Brake Hoses | ✓ | | |
| Battery & Battery cables | ✓ | | |
| Belts & pulleys | ✓ | | |
| No Abnormal Engine Odour | ✓ | | |
| Suspension & Shock absorbers | | ✓ | |
| Tie Rods & Steering Rack | | ✓ | |
| Axels | ✓ | | |
| Transmission oil leak free | ✓ | | |
| Transfer case | ✓ | | |
| Differential | ✓ | | |
| Wheel Bearings | | ✓ | |
| Exhaust System | ✓ | | |
| Undercarriage | ✓ | | |

| ELECTRONIC DIAGNOSTIC | | | |
|--|---|--|--|
| Engine | ✓ | | |
| Engine Control Unit | ✓ | | |
| Transmission | ✓ | | |
| Braking System | ✓ | | |
| Airbag System | ✓ | | |
| Air Conditioning System | ✓ | | |
| Instrument Cluster and Warning Lights | ✓ | | |
| Driving Electronics (e.g. Headlights, power steering, indicators, Brake Lights, Tail Lights) | ✓ | | |
| Driving Convenience features (E.g. cruise control, parking sensors, reversing camera.) | ✓ | | |
| Navigation | ✓ | | |
| Windows & Sunroof | ✓ | | |


| INTERIOR INSPECTION | | | |
|--|---|--|--|
| Interior Trims | ✓ | | |
| Carpets | ✓ | | |
| Upholstery Front Seats | ✓ | | |
| Upholstery Rear Seats | ✓ | | |
| Audio System | ✓ | | |
| Smoke Odour | ✓ | | |
| Gauges (speedometer, tachometer, temperature, oil pressure, and amp meter) | ✓ | | |
| Seat Belts | ✓ | | |

| TIRES & BRAKES | | | |
|--|---|--|--|
| Matching tires (brand, year, pattern) | ✓ | | |
| Car Rims (scratch & dent free) | ✓ | | |
| Front brake pads: <u>40</u> % | ✓ | | |
| Front brake discs | ✓ | | |
| Rear brake pads: <u>40</u> % | ✓ | | |
| Rear brake discs | ✓ | | |
| All lug nuts in place | ✓ | | |
| All trunk tools available | ✓ | | |
| Spare tire available in car (where applicable) | ✓ | | |
| Front left tire with date: <u>2016</u> , depth: <u>50</u> % | ✓ | | |
| Front right tire with date: <u>2016</u> , depth: <u>50</u> % | ✓ | | |
| Rear left tire with date: <u>2016</u> , depth: <u>50</u> % | ✓ | | |
| Rear right tire with date: <u>2016</u> , depth: <u>50</u> % | ✓ | | |

| ROAD TEST | | | |
|--|---|--|--|
| Keyless Entry | ✓ | | |
| Steering wheel alignment | ✓ | | |
| Cruise Control | ✓ | | |
| Auto Gear Box Changes | ✓ | | |
| Drives straight on level ground | ✓ | | |
| Transmission/Clutch | ✓ | | |
| Brakes Noise | ✓ | | |
| Suspension noises | ✓ | | |
| Tyre noise | ✓ | | |
| 4 wheel drive system | ✓ | | |
| Engine vibration and noise | ✓ | | |
| Interior noise | ✓ | | |
| Steering condition during lock-to-lock | ✓ | | |

FINDING: No Major Scratches Found On This Car's Body

**BODY INSPECTION
REPORT**



** To get the best Estimate for Repair Work found on this car, please contact Open Bonnet at +971589512500*